

000 1620  
 001 000  
 002 016  
 003  
 004  
 005 Department Of Natural Resources And Environmental Control  
 006  
 126 L3 02966  
 140 Architectural Drawings  
 200 1949  
 210 1991  
 220 1949-1970, 1991  
 240 1.3 cu.ft.  
 241 cf box, oversize folder  
 261 Office copy of the installations of sanitary systems. The 1991 record  
 is for the spray irrigation facilities for "Appoquin" near Odessa.  
 270  
 290  
 310  
 329 WORK STATUS ARCHIVIST:  
  
 needs sorting  review for identification/  
 needs unfolding further determination  
 needs foldering/reboxing  processing  
 other: \_\_\_\_\_  determine origin/purpose  
 other: \_\_\_\_\_  
  
 CONDITION: FILM:  
 totally disorganized  for security  
 order not apparent  destroy original  
 origin questionable  other: \_\_\_\_\_  
 other: \_\_\_\_\_  
  
 330 No apparent arrangement  
 331 No index.  
 332  
 350  
 360 fair; acid damage; storage damage; dirt damage; metal fasteners  
 390  
 430  
 900  
 990 8/30/1996  
 995 September 12, 1996; November 18, 1996; February 20, 1997; July 3, 2001;  
 July 12, 2001  
 999 Data entry sheets, to list drawings, were not kept in order. Therefore,  
 the checklist that will be created will not be accurate.  
 bhh