000 5100
001 000
002 211
003
004
005 City of Wilmington
006 Water Department
140 Service Register
141
142
200 1897
210 1903
220
241 1 volume; 0.13 cubic feet
261 Record of services from the main to the curb.
27X Register shows order numbers (old and new), date of entry, owner and street location, size of main, distance from the curb, depth, size, length, and cost of service pipe, size and cost of ferrule, style and cost of stop box, cost of paving, labor, ferrule book, building book, total cost, and remarks.
29X Spine missing. "Services Main to Curb, 1897 to 1903" written on spine.
310
329 WORK STATUS

___needs sorting
___needs unfolding
___needs foldering/reboxing
___other: _____

CONDITION:

___totally disorganized
___order not apparent
___origin questionable
___other:_____

ARCHIVIST:

___review for identification/ further determination
___processing
___determine origin/purpose
___other:

FILM:

___for security
___destroy original
___other:

330 Arranged numerically by original work order number.
331 NONE
332 Form printed w/writing
350
360 Poor; acid damage; storage damage; dirt damage; spine missing and cover torn.
390 NONE
430 Transferred in early 1988.
900
990 8/2/95
995 April 9, 1996; May 2, 1996; May 22, 1997
999 Not sure of some of the columnar headings. Transfer included six other volumes.
bhh